						Invoice#	729263T	
	FIED	DIINDL	15	IHIES		Date:	10/6/2020	
						WO#	729263	
	6205 E KELLO	DGG WICHITA, KS 67218		e# (316) 681 3382		<b>VV</b> O#	129203	
		www.reddiindustries.	com					
Bill To:	128561 Leroy Gray			Locatio	Location: 127003 Leroy Gray			
	3970 SW 100th St				3970 SW 100th	n St		
	Augusta,KS 67010	I			Augusta,KS 67	010		
Tech Code					Service Date			
65008 FURLONG - DAVID					10/6/2020			
heating and	08 FURLONG - DAVID AC are working proper omer is at work teachin ne.	Service Date: 10/06/2020]] p y at this time. Please see att g and can't be reached until	ached	checklists. Replaced 2 -	16x25x1 filters. Old o	ones were dirty a	and restrictive to	
Solution Code Item Description Sales Amount								
							16.10	
						160.00		
					Invoice Total \$		176.10	
Payment: Method: /	<b>Amt:</b> \$176.	<b>Amt:</b> \$176.10 <b>Method: Ref:</b>		<b>Amt:</b> \$0.00				
SubTotal:	\$176.10		Tax:	\$0.00 <b>Tot</b> a	l: \$176.10	Total due:	\$176.10	
127003 - Leroy	∕ Gray Call# 729263 . Ma	anu: Lennox Model# G24M3-75A	-12 Sr#	6300L 10964 Loc# Hall clos				
	TUNE UP AND SAFETY II		.2 01#					
[X]CHANGE FILTERS								
[X] CLEAN FLAME SENSOR								
[X] CHECK FOR GAS LEAKS [X] COMPLETE FURNACE CYCLE								
[X] CLEAN BURNER CONTROLS								
[X] CHECK GAS PRESSURE TO BURNER MANIFOLD								
[X] CHE	CK FAN CONTROL							
L								

[X] CHECK DRAFT OF FLUE

[X] TEMP IN 75 TEMP OUT 125 RISE 50

[X] PREFORM CARBON MONOXIDE TEST 0 ppm

127003 - Leroy Gray Call# 729263 . Manu: Lennox Model# HS26-036-2P Sr# 5801F26916 Loc# Outside

AC TUNE UP AND SAFETY CHECK

CHECKED THERMOSTAT FOR OPERATION: YES [X]

CHECKED FILTER: YES [X] 16x25x1(x2) FILTER SIZE X X

CHECKED CONDENSATE LINE: YES [X]

CHECKED ALL ELECTRICAL COMPONENTS: YES [X]

CHECKED AMP DRAW ON CONDENSER FAN MOTOR: YES [X] READING = 0.7 amps

REFRIGERANT PRESSURES: R22 [X] 410A SUCTION/LIQUID LINES PSIG, OUTSIDE TEMP 75 DEG F

CHECKED SCHRADER VALVE FOR LEAKS: YES [X]

INSPECTED UNIT INSULATION YES [X]

TEMP AIR AT INDOOR REGISTER 52 DEG F

NOTES: 20\* temp drop