

Broker Disclosure 9519 SW Santa Fe Lake Rd

The home is on a septic tank and lateral field sewer disposal system.

There are 2 breaker panels one in the breezeway by the storm shelter and one in the master bedroom.

The furnace and hot water tank are propane. Propane tank is leased.

The well controls and pressure tank are in the storm shelter.

There are 3 water hydrants. Hydrant #1 on the north side of the garage is hooked to rural water. Hydrants #2 and #3 are in front of the home and in the back yard. They are hooked to the well.